

Import Performance INC
 5618 Hillsborough Street
 Raleigh, NC 27606
 (919) 854-2626
 Service@Importperformance-nc.com
 www.importcarnc.com

Repair Order # 32928

1981 Fiat 124 Spider

License #

Inv Date: 12/03/2020 @ 2:13pm

Continued from previous page

<p>Warranty Standard Warranty is 12 months or 12k miles</p> <p>I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.</p> <p><input checked="" type="checkbox"/> _____ Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.</p> <p><input checked="" type="checkbox"/> _____ Customer acknowledges receipt of merchandise and services.</p>	<p>Tax Breakdown: Default Sales Tax 78.16</p>	<p>Repair Order Summary: Parts 235.00 Labor 773.50 Supply Charge/H 59.00</p> <p>Sub Total 1,067.50 Sales Tax (DEF) 78.16</p> <p>Total 1,145.66</p>
<p>Page 2 of 2</p>	<p>Discard old parts</p>	<p>Original Estimate:</p>

Repair Order # 32928

1981 Fiat 124 Spider

VIN: ZFAAS00B8B8180078
 Engine: L4 2.0L, 122cid, DOHC, GAS, FI
 Trans:

License #
 ODO In:18861
 Color:
 Mfg. Date:
 Unit #

Inv Date: 12/03/2020 @ 2:13pm
 Service Writer: John Elliason
 Status: 5. Work In Progress 11/12/1.0
 Driver:
 PO #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
->> blower fan is not working						0.00
->> Lights for the gauges are not working						0.00
->> When ignition off and turn park light clock stops						0.00
						0.00
->> see if any coolant leaks , some spots showed - review						0.00
						0.00

The Vehicle needs the following General Repairs.

1,008.50

Check blower motor
 Remove as needed
 Found locked up electrical blower motor
 Replace with used as needed.
 Had to remove ebrake
 Had to remove shifter assembly
 Had to remove steering column
 Had to remove center console

Check instrument cluster lights / fiber optic, reostat delete
 Repair as needed - rewiring as needed

Check clock operation
 rewiring as needed

Checked coolant leak
 tighten loose hose clamp as needed
 pressure checked - OK

Labor Service - General Repairs	6.50		119.00	773.50
New FIAT 124 SPIDER 76 B FIAT 124 SPIDER 76 BLOWER BOX AND MOTOR FAN		1.00	235.00	235.00

Import Performance INC
 5618 Hillsborough Street
 Raleigh, NC 27606
 (919) 854-2626
 Service@Importperformance-nc.com
 www.importcarnc.com

Repair Order # 32928

1981 Fiat 124 Spider

License #

Inv Date: 12/03/2020 @ 2:13pm

Continued from previous page

Warranty
 Standard Warranty is 12 months or 12k miles

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and /or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

 Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

 Customer acknowledges receipt of merchandise and services.

Tax Breakdown:
 Default Sales Tax 78.16

Repair Order Summary:
 Parts 235.00
 Labor 773.50
 Supply Charge/H 59.00

Sub Total 1,067.50
 Sales Tax (DEF) 78.16

Discard old parts

Original Estimate:

Total 1,145.66

Packing Slip

1565 Howard Access Rd
Ste A
Upland, CA 91786

Ship To:

Order # 1673
Date 9/5/2020
User 3362524594230
Ship Date 9/5/2020

Item	Description	Price	Qty	Ext. Price
AA000800	Chrome Lug Bolts for Rota and Competizione Monza Wheels	\$44.00	1	\$44.00
AA001260	NRG 365mm Light Wood Steering Wheel	\$199.00	1	\$199.00
AA000750	Competizione Sport Tuning Monza Wheels 15 x 6.5 (Gunmetal), set of 4	\$470.00	1	\$470.00

Sub Total: \$713.00
Shipping: \$87.26
Total: \$800.26



once files are downloaded
instructions of damage will be called
the wheels on a car will cause
the wheels to turn slow as in
the wheels of the car will
the wheels will have had
the wheels of the car will
the wheels will have had
the wheels of the car will
the wheels will have had
the wheels of the car will

Retail Invoice
144692
Printed/Emailed on 09/21/2020
Emailed to



Store# 348052
In: 09/21/20 03:48PM
Out: 09/21/20 06:57PM

www.FirestoneCompleteAutoCare.com

Cust Status: Drop Off Appt: No FINAL INVOICE

CARY - DAVIS DR - 1717 HIGH HOUSE RD, CARY, NC. 27513-3601 - 919.469.1450

Service Advisor: 5 GABRIELLE

Wheel Lock: N

Technician: 09 JOHN

Customer Details:

Alt. Auth. Name & Phone:

Vehicle Details:

N/A

1981 Fiat SPIDER BASE

VIN #:
LIC #: 188840 NC
MILEAGE: 18,840

Description	Rev Hist /Article # ID	Qty	Unit Price	Extended Price	Job Total
YOKOHAMA TIRE PACKAGE					485.48
110170132 ADVAN FLEVA BW 205/55R15 88V No Mileage	7099615 09TN	4	118.99	475.96	
Warranty					
DOT# FDH7LC90719					
DOT# FDH7LC90719					
DOT# FDH7LC93918					
DOT# FDH7LC93918					
NORTH CAROLINA TIRE FEE	7095931 09NN	4	2.38	9.52	
SIMPLE TIRE INSTALL 50 SERIES & ABOVE					65.99
RUBBER VALVE STEM	7015040 09TN	1	3.99	3.99	
SIMPLE TIRE INSTALLATION 50-SERIES & ABO	7034282 09TS	4	8.80	35.20	
SIMPLE TIRE WHEEL BALANCE LABOR	7034285 09TS	4	6.70	26.80	

ORDER NOTES

CALL WHEN TIRES ARRIVE

INSPECTION

CUSTOMER REQUESTED NO INSPECTION

All parts are new unless otherwise specified.

Payment History:

Visa 4735 519.99 057353 Sale

Term: 0001 Manual Entry

Debit 4735 75.43 048408 Sale

MID: 222220328365

Term: 0001 Card Inserted

AID:A0000000980840

Total Tendered PIN VERIFIED 595.42

Summary:

Parts	479.95
Labor	71.52
Shop Supplies	4.34
Sub-Total	555.81
Tax (7.25%)	39.61
Total	\$595.42

Information on tire warranty, maintenance, and safety can be located at
<https://www.firestonecompleteautocare.com/tires/warranty-options/>
or by calling toll free 800-847-3272 to obtain a free printed copy

Information on service warranty, maintenance, and safety can be located at
<https://www.firestonecompleteautocare.com/maintain/service-warranty-options/>



Auto Ricambi, LLC

6705 Colleyville Blvd.
Colleyville, TX 76034

E-mail: info@autoricambi.us
Web Site: http://www.autoricambi.us
Phone: 682-233-3428

Sales Receipt Commercial Invoice

Date	Sale No.
9/24/2020	82614

Sold To

Ship To

Order Date	Ship Via	Email	Payment Method	Model	Order No.
9/24/2020	Federal Express		Visa		82614
Qty	SKU	Description	Rate	Amount	
1	EL7-480	Hazard switch - FIAT Spider 2000 1979-82	99.99	99.99	
1	IG0-200	Ignition Tune-up Kit - Fiat Spider 2000 1979-85 1 x IG1-124 AR distributor cap & rotor kit 4 x IG7-012 Champion spark plugs 1 x IG7-421 8mm spark plug wire set 1 x IG3-429 AR magnetic pick up	95.99	95.99	
1	RE2-461	Door glass weatherstrip set - FIAT 124 (with felt)	32.99	32.99	
1	SHIPPING O...	Online Shipping & Insurance Shipment Carrier: ; Shipment Method: FedEx Air (2nd Day) Payment Method: Credit Card; Transaction ID: PL0050729435	17.67	17.67	
<p>Auto Ricambi, LLC makes no representations or warranties, either express or implied, of any kind with respect to the products sold by Auto Ricambi, LLC. All warranty claims are the responsibility of the manufacturer. For a full listing of the Auto Ricambi Terms and Conditions please visit www.AutoRicambi.us</p>				Subtotal	\$246.64
				Sales Tax (0.0%)	\$0.00
				Total	\$246.64

Packing Slip

1565 Howard Access Rd
Ste A
Upland, CA 91786

Ship To:

Order # 1688
Date 9/15/2020
User 3362524594230
Ship Date 9/15/2020

Item	Description	Price	Qty	Ext. Price
AA001140	Fiat Spider 95 Amp Alternator Conversion	\$197.00	1	\$197.00
			Sub Total:	\$197.00
			Shipping:	\$16.82
			Total:	\$213.82



Vick Autosports, Inc.

601 E Chambers St
Cleburne, TX 76031
USA



INVOICE

Invoice Number: 57429
Invoice Date: Sep 8, 2020
Page: 1

Voice: 817 483-9933
Fax: 817 483-1104
Email: info@vickauto.com

Bill To:

Ship to:

Customer ID	Customer PO	Payment Terms	
		Prepaid	
Sales Rep ID	Shipping Method	Ship Date	Due Date
Webstore	FedEx Ground		9/8/20

Quantity	Item	Description	Unit Price	Amount
1.00	81-4313-KIT	Fiat Silver Emblem Kit - 2 X 81-4313, 4 X 81-4631, 2 X 81-4650	46.99	46.99
Shipping & Handling		8.50		
Subtotal				46.99
Sales Tax				
Total Invoice Amount				Continued
Balance - Negative/Positive				0.00
Amount Paid				55.49

Check/Credit Memo No: 4735

All shipments are insured by the shipping company and not by VAS. Per our 'Terms of Service' it is your responsibility to immediately shipping company about any damaged goods. Keep all shipping contents, boxes, and packaging material for inspection purposes of tt shipping company. If you don't follow these instructions, most shipping companies will deny your claim.



M & T Manufacturing Co.
 Convertible Top Guys
 30 Hopkins Lane
 South Kingstown, RI 02879
 401-789-0472 Fax: 401-789-3700

10/5/2020
 Invoice #: 227447
 Page: 1

Ship To:

Bill To:

Phone:
 Cust PO: 170042
 Reference: 81 FIAT SPIDER
 Terms: PAYPAL
 Ship Via: UPS GROUND
 Salesperson: CAITLIN

Stock Code	Description	Taxable	Quantity	Price	Extended
FIAT LATE 79-85 848SF	LATE 79 -85 FIAT SPIDER TOP W/PRC BLACK STAYFAST 848 SF	Y	1.00	439.9500	439.9500
>BOJO	Plastic Pry Bar Tool, Great for popping out pop rivets in headliner and top frame		1.00		
>C-815-848SF	79-85 FIAT SPIDER TOP WITH PC, BLACK STAYFAST- 9lb BLACK STAYFAST#848		1.00		
>CAU2	UNIVERSAL FOREIGN; Side tension cables. <A95>		1.00		
>HH-66-4OZ	GLUE WITH BRUSH. VOC CONTENT 254 GRAMS PER LITER 4 OZ CONTAINER		1.00		
>IN-FIAT 124	FIAT 124 INSTRUCTIONS		1.00		

Cancelled

paid \$25.00

**SOME ITEMS IN YOUR ORDER
 HAVE SHIPPED SEPARATELY
 PLEASE EXPECT
 ANOTHER PACKAGE**

SubTotal: 439.95
 Tax: 0.00
 Shipping: 34.29
 Total: 474.24
 Paid: 474.24
 Balance: 0.00

Check: 474.24

ALL RETURNS REQUIRE A RMA NUMBER, PLEASE CALL 401-789-0472 FOR THIS NUMBER, RETURNS WITHOUT THIS NUMBER WILL BE REFUSED



Milex Complete Auto Care / Mr. Transmission
 303 Bowden St
 Cary, North Carolina 27513
 (919) 465-4488
 carymrtmilex.com



1981 FIAT 124 SPIDER 2000
 Plate :
 ODO : 18,840
 V.I.N. : ZFAAS00B6B8186753
 Unit #:
 Engine: 2.0L I4 F

INV # : 7573
 Date : 08/31/2020
 Time :
 PO # :
 REG # :
 Tech. : PAUL/HEATHER

B#:	H#:			Parts Ea.	Tot.Parts	Labour	Tx	Total	C
Qty	Hrs.	Description							
1.00		Interstate MTP 48/H6		202.95	202.95		TAX	202.95	

WO# 9041 Copyright 2020 Autogence Inc. - LANKAR 11.12

Milex Complete Auto Care / Mr. Transmission #585
 DBA: Yella Horse Investments Inc. 303 Bowden Street Cary, NC 27513
 Tel.#: (919) 465-4488 Fax: (919) 465-4482

LIMITED WARRANTY TERMS*:

- _____ Category # 1 - Under the car and/or under the hood repairs - 12 months or 12,000 miles or if TechNet approved 24 months or 24,000 miles.
- _____ Category # 2 - Rebuild /Repaired transmission assembly - 12 months or 12,000 miles. Requires 14 day fluid/leak recheck.
- _____ Category # 3 - Remanufactured transmission replacement - 36 months or 100,000 mile limited parts and labor through manufacturer. Requires 14 day fluid/leak recheck.
- _____ Category # 4 - No Parts or Labor Warranty expressed or implied.
- _____ Category # 5 - Decline of service or recommended repair - No Warranty expressed or implied. (Customer may be required to sign General Release)
- _____ Category # 6 - Brake Friction Material (Pads or Shoes) - Limited Lifetime on Pads and Shoes for defects only. Labor and any additional Parts - 12 Months or 12,000 Miles.
- _____ Category # 7 - AC Repair - 12 Months on parts and 6 months on labor.
- _____ Category # 8 - Used parts - 90 day replacement, parts only. Labor for installation Used Parts is not covered.

*Excluding Oil Changes & Decline of Service

If no warranty category is specified above according to the warranty provisions attached/back then warranty will be 30 days or 1000 miles, or state minimum requirement. Limited lifetime warranty only applies to particular brake materials, transmission lifetime warranties are not valid and will not be honored.

Center's Activation Signature _____

PAID BY...
 08/31/2020 Visa 217.66

Undersigned received the vehicle specified above with a copy of this work order and agrees to pay the amount listed. A signature here confirms that Undersigned has opportunity to have the all work clearly explained and has reviewed all the line items and the work performed including, but not limited to, the work order, performance check and any Warranty Provision. Undersigned agrees to all terms listed within, as well as I understand that all information to be correct. Signature serves as final confirmation to all initial authorization and any phone authorization that may have been given to the center pertaining to services rendered. In the event that Undersigned fails to pay invoice in full, any given warranty within the repair order will become null and void. As to this indebtedness, I wave all rights of exemption. I agree to pay in full for all services rendered, including all costs.

Sub Tot.	202.95	0.00	202.95
		TAX	14.71
		Deductible	0.00
		Total	217.66



Auto Ricambi, LLC

6705 Colleyville Blvd.
Colleyville, TX 76034

E-mail: info@autoricambi.us
Web Site: http://www.autoricambi.us
Phone: 682-233-3428

Sales Receipt Commercial Invoice

Date	Sale No.
9/7/2020	82052

Sold To

Ship To

Order Date	Ship Via	Email	Payment Method	Model	Order No.
9/7/2020	Federal Express		PAY PAL		82052
Qty	SKU	Description	Rate	Amount	
2	EL3-416	Running Light Bulb - For tail lights and 1974 and earlier front lights - 5 watt	2.19	4.38	
1	EX4-035	Exhaust Clamp for EX8-428 rear muffler - Used at the junction of the center and rear mufflers	3.99	3.99	
1	EX4-428	Hanger for ANSA performance rear muffler - FIAT 124 (required for to maintain warranty on EX8-428-Z)	7.99	7.99	
1	EX8-428-Z	Free flow ANSA Twin-tip performance rear muffler - FIAT 124 (Must use EX4-428 Ansa recommended hanger - required to insure warranty)	299.99	299.99	
1	RE5-499	Convertible top catch pair in chrome - FIAT 124 1979-85 - 8mm pin and located on windshield frame	119.99	119.99	
2	RE7-404	Top boot hook at body - FIAT 124 1968-82	18.99	37.98	
2	RE7-405	Top boot hook at body gasket - FIAT 124 all	2.29	4.58	
1	RI8-476	Door guide (or lug) set - FIAT 124 all Original solid rubber	24.99	24.99	
1	RS7-474	License plate light pair - Spider 1975-85	209.99	209.99	
Shipment Carrier: ; Shipment Method: FedEx (Ground) Payment Method: PayPal; Transaction ID: 31S125086P2672305					
Auto Ricambi, LLC makes no representations or warranties, either express or implied, of any kind with respect to the products sold by Auto Ricambi, LLC. All warranty claims are the responsibility of the manufacturer. For a full listing of the Auto Ricambi Terms and Conditions please visit www.AutoRicambi.us				Subtotal	\$713.88
				Sales Tax (0.0%)	\$0.00
				Total	\$713.88

Midwest-Bayless Italian Auto

1333 Kingry Street
Columbus, OH 43211
US

(614) 784-8870

Order Information

COMMERCIAL INVOICE

*** PLEASE RETAIN FOR FUTURE REFERENCE ***

Midwest-Bayless Italian Auto -
Fiat and Lancia Parts

Midwest-Bayless
1333 Kingry St.
Columbus, OH 43211
UNITED STATES

parts@midwest-
bayless.com
http://www.midwest-
bayless.com
614-784-8870

Order Number 134832
Customer ID 20819765
Order Date 8/30/2020 7:12:02 AM


Bill To:

Ship To:

Order Date: 8/30/2020 7:12:02 AM

Locale/Currency: en-US / USD

Payment Method: PAYPALEXPRESS

SKU:	Product	Quantity	Price	Sale Price	Discount	Ext. Price
 WD-209	Wiring Diagrams Manual (Fiat 124 Spider 1981-82) - NEW-WD-209 Vehicle: Fiat - 124 S-C - 0 [Location: OFFICE F1] [SKU: WD-209]	1	\$19.79	\$14.79		\$14.79

Order Notes:

None

SubTotal: \$14.79
Shipping: First-Class™
Package Service \$3.97
Tax: \$0.00
Total: \$18.76

Thank you for doing business with Midwest-Bayless!

1-800-241-1446

parts@midwest-bayless.com



Auto Ricambi, LLC

6705 Colleyville Blvd.
Colleyville, TX 76034

E-mail: info@autoricambi.us
Web Site: http://www.autoricambi.us
Phone: 682-233-3428

Sales Receipt Commercial Invoice

Date	Sale No.
9/14/2020	82282

Sold To

Ship To

Order Date	Ship Via	Email	Payment Method	Model	Order No.
9/14/2020	Federal Express		PAY PAL		82282

Qty	SKU	Description	Rate	Amount
1	RI8-498-A	Arm rest long chrome trim strip - Pair	17.99	17.99
2	RI8-499	Arm rest chrome trim plug - FIAT 124 all	4.99	9.98
1	RS0-002	Factory Shop Manual - Spider 1975-85	59.99	59.99
1	RS0-173	DANGER - Don't Touch and Don't Disconnect... Ignition Decal. Fiat all	4.99	4.99
1	SHIPPING O...	Online Shipping & Insurance Shipment Carrier: ; Shipment Method: FedEx Air (2nd Day) Payment Method: PayPal; Transaction ID: 02740943JL8999626	20.73	20.73

Auto Ricambi, LLC makes no representations or warranties, either express or implied, of any kind with respect to the products sold by Auto Ricambi, LLC. All warranty claims are the responsibility of the manufacturer. For a full listing of the Auto Ricambi Terms and Conditions please visit www.AutoRicambi.us

Subtotal	\$113.68
Sales Tax (0.0%)	\$0.00
Total	\$113.68



Auto Ricambi, LLC

6705 Colleyville Blvd.
Colleyville, TX 76034

E-mail: info@autoricambi.us
Web Site: http://www.autoricambi.us
Phone: 682-233-3428

Sales Receipt Commercial Invoice

Date	Sale No.
9/28/2020	82722

Sold To

Ship To

Order Date	Ship Via	Email	Payment Method	Model	Order No.
9/28/2020	Federal Express		PAY PAL		82722

Qty	SKU	Description	Rate	Amount
1	EL3-450	Interior light bulb - 124 Spider 1968-on	2.99	2.99
1	EL3-472	Interior light - FIAT 124 Spider 1968-82	26.99	26.99
1	SHIPPING O...	Online Shipping & Insurance Shipment Carrier: ; Shipment Method: FedEx Air (2nd Day) Payment Method: PayPal; Transaction ID: 8CE60913XS846694R	14.81	14.81

<p>Auto Ricambi, LLC makes no representations or warranties, either express or implied, of any kind with respect to the products sold by Auto Ricambi, LLC. All warranty claims are the responsibility of the manufacturer. For a full listing of the Auto Ricambi Terms and Conditions please visit www.AutoRicambi.us</p>	Subtotal	\$44.79
	Sales Tax (0.0%)	\$0.00
	Total	\$44.79



Auto Ricambi, LLC

6705 Colleyville Blvd.
Colleyville, TX 76034

E-mail: info@autoricambi.us
Web Site: http://www.autoricambi.us
Phone: 682-233-3428

Sales Receipt Commercial Invoice

Date	Sale No.
10/19/2020	83357

Sold To

Ship To

Order Date	Ship Via	Email	Payment Method	Model	Order No.
10/19/2020	Federal Express		PAY PAL		83357
Qty	SKU	Description	Rate	Amount	
1	RS0-024	Fiat leather key chain / fob	5.99	5.99	
1	RS0-026	Pininfarina key chain / fob	10.99	10.99	
1	SHIPPING O...	Online Shipping & Insurance	9.10	9.10	
		Shipment Carrier: ;			
		Shipment Method: Economy - Limited Tracking (Domestic Economy)			
		Payment Method: PayPal; Transaction ID: 9BU67043VN4622633			

<p>Auto Ricambi, LLC makes no representations or warranties, either express or implied, of any kind with respect to the products sold by Auto Ricambi, LLC. All warranty claims are the responsibility of the manufacturer. For a full listing of the Auto Ricambi Terms and Conditions please visit www.AutoRicambi.us</p>	Subtotal	\$26.08
	Sales Tax (0.0%)	\$0.00
	Total	\$26.08



Milex Complete Auto Care / Mr. Transmission
 303 Bowden St
 Cary, North Carolina 27513
 (919) 465-4488
 carymrtdmilex.com



1981 FIAT 124 SPIDER 2000
 Plate :
 ODO : 1,840
 V.I.N. : ZFAAS00B8B8180078
 Unit #:

INV # : 7673
 Date : 09/16/2020
 Time :
 PO # :
 REG # :

Engine: 2.0L I4 F

Tech. : MICHAEL/HEATHER

B#:	H#:	Description	Parts Ea.	Tot. Parts	Labour	Tx	Total	C
		Attach rear muffler to exhaust pipe making sure that all clearances are optimal *****				TAX		
1.00		Cut Muffler Pipe Down To Fit. Welded Pipe. Added J-Hook Hanger To Hold Exhaust (Heavy In The Rear)			110.00	TAX	110.00	
		WARRANTY LABOR				TAX	-110.00	
		Thank you for the referral`s and continued business!				TAX		
		This one is on us;				TAX		
		Heather and Steve				TAX		

WO# 9152

Copyright 2020 Autogence Inc. - LANKAR 11.12.

Milex Complete Auto Care / Mr. Transmission #585
 DBA: Yella Horse Investments Inc. 303 Bowden Street Cary, NC 27513
 Tel.#: (919) 465-4488 Fax: (919) 465-4482

LIMITED WARRANTY TERMS:

- _____ Category # 1 - Under the car and/or under the hood repairs - 12 months or 12,000 miles or if TechNet approved 24 months or 24,000 miles.
- _____ Category # 2 - Rebuild /Repaired transmission assembly - 12 months or 12,000 miles. Requires 14 day fluid/leak recheck.
- _____ Category # 3 - Remanufactured transmission replacement - 36 months or 100,000 mile limited parts and labor through manufacturer. Requires 14 day fluid/leak recheck.
- _____ Category # 4 - No Parts or Labor Warranty expressed or implied.
- _____ Category # 5 - Decline of service or recommended repair - No Warranty expressed or implied. (Customer may be required to sign General Release)
- _____ Category # 6 - Brake Friction Material (Pads or Shoes) - Limited Lifetime on Pads and Shoes for defects only. Labor and any additional Parts - 12 Months or 12,000 Miles.
- _____ Category # 7 - AC Repair - 12 Months on parts and 6 months on labor.
- _____ Category # 8 - Used parts - 90 day replacement, parts only. Labor for installation Used Parts is not covered.

*Excluding Oil Changes & Decline of Service

Undersigned received the vehicle specified above with a copy of this work order and agrees to pay the amount listed. A signature here confirms that Undersigned has opportunity to have the all work clearly explained and has reviewed all the line items and the work performed including, but not limited to, the work order, performance check and any Warranty Provision. Undersigned agrees to all terms listed within, as well as I understand that all information to be correct. Signature serves as final confirmation to all initial authorization and any phone authorization that may have been given to the center pertaining to services rendered. In the event that Undersigned fails to pay invoice in full, any given warranty within the repair order will become null and void. As to this indebtedness, I wave all rights of exemption. I agree to pay in full for all services rendered, including all costs.

Other Charges				-110.00
Sub Tot.	0.00	110.00		0.00
		TAX		0.00
		Deductible		0.00
		Total		0.00



Milex Complete Auto Care / Mr. Transmission
 303 Bowden St
 Cary, North Carolina 27513
 (919) 465-4488
 carymrtmilex.com



1981 FIAT 124 SPIDER 2000
 Plate :
 ODO : 1,840
 V.I.N. : ZFAAS00B8B8180078
 Unit #:

INV # : 7673
 Date : 09/16/2020
 Time :
 PO # :
 REG # :

Engine: 2.0L I4 F

Tech. : MICHAEL/HEATHER

B#: H#:

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labour	Tx	Total	C
-----	------	-------------	-----------	-----------	--------	----	-------	---

If no warranty category is specified above according to the warranty provisions attached/back then warranty will be 30 days or 1000 miles, or state minimum requirement. Limited lifetime warranty only applies to particular brake materials, transmission lifetime warranties are not valid and will not be honored.

Center's Activation Signature _____

PAID BY:...

Undersigned received the vehicle specified above with a copy of this work order and agrees to pay the amount listed. A signature here confirms that Undersigned has opportunity to have the all work clearly explained and has reviewed all the line items and the work performed including, but not limited to, the work order, performance check and any Warranty Provision. Undersigned agrees to all terms listed within, as well as I understand that all information to be correct. Signature serves as final confirmation to all initial authorization and any phone authorization that may have been given to the center pertaining to services rendered. In the event that Undersigned fails to pay invoice in full, any given warranty within the repair order will become null and void. As to this indebtedness, I wave all rights of exemption. I agree to pay in full for all services rendered, including all costs.

Other Charges								-110.00
Sub Tot.	0.00	110.00						0.00
TAX								0.00
Deductible								0.00
Total								0.00



Auto Ricambi, LLC

6705 Colleyville Blvd.
Colleyville, TX 76034

E-mail: info@autoricambi.us
Web Site: http://www.autoricambi.us
Phone: 682-233-3428

Sales Receipt Commercial Invoice

Date	Sale No.
9/3/2020	81945

Sold To

Ship To

Order Date	Ship Via	Email	Payment Method	Model	Order No.
9/3/2020	Federal Express		PAY PAL		81945
Qty	SKU	Description	Rate	Amount	
2	RI9-460	Seat adjusting knob - Fiat 124 1980on - Improved design	24.59	49.18	
1	SHIPPING O...	Online Shipping & Insurance Shipment Carrier: ; Shipment Method: Economy - Limited Tracking (Domestic Economy) Payment Method: PayPal; Transaction ID: 6EW94497PW6225340	8.75	8.75	
<p>Auto Ricambi, LLC makes no representations or warranties, either express or implied, of any kind with respect to the products sold by Auto Ricambi, LLC. All warranty claims are the responsibility of the manufacturer. For a full listing of the Auto Ricambi Terms and Conditions please visit www.AutoRicambi.us</p>				Subtotal	\$57.93
				Sales Tax (0.0%)	\$0.00
				Total	\$57.93



C. OBERT & CO.

ALL MAIL TO: PO BOX 643, 95061
SANTA CRUZ, CA 95060
(831) 423-0218
1-6 M,T,Thur

INVOICE

Transaction #: 28605
Account #: 0007471
Page: 1 of 1
Date: 9/6/2020
Time: 2:49:21 PM
Cashier: 1
Register #: 4

Bill To:

Ship To:

Reference: 3385
Comment: Do these include retainer clips?

Rep	Item Lookup Code	Description	Quantity	Price	Extended
	0000009483N	PININFARINA "f" SIDE EMBLEM	2	\$24.50	\$49.00

C. OBERT & CO. TERMS AND CONDITIONS:
 NO RETURNS WILL BE EXCEPTED
 WITHOUT A COPY OF THIS INVOICE
 SPECIAL ORDERS AND ELECTRICAL
 PARTS ARE NOT RETURNABLE. ALL
 RETURNS ARE SUBJECT TO A 5%
 RESTOCKING FEE, RETURN TO 301
 ENCINAL ST, SANTA CRUZ, CA 95060.



28605

Sub Total	\$49.00
Sales Tax	\$0.00
UPS Ground	\$18.56
1Z9607990367956034	
Total	\$67.56
PayPal Tendered	\$67.56
Change Due	\$0.00

1981 Fiat 124 Spider, L4 2.0L, 1995cc, DOHC, GAS, FI

10.31.2014 -

Item Number	Description	Quantity	Price	Sale	Extension	Warranty	Tech 1	Tech 2
No Start	No Start							
DIAGNOSE	Diagnose time	1.00		95.55	95.55		HMP	
Fuel Pump - NR	The Fuel Pump needs to be repaired or replaced. Technician st							
FUEL SYSTEM	Fuel System - Repair	5.00		95.55	477.75		HMP	
0 332 514 121	Relay Fuel Injection System 2050	1.00	153.00	153.00	153.00			
69 430	Fuel Pump 2040	1.00	236.22	236.22	236.22			
1263	Spark Plug BP6ET NGK 2045	1.00	5.33	5.33	5.33			
71 028	Fuel Filter	1.00	22.32	22.32	22.32			
GASOLINE	Fuel Needed For Repairs	1.00	31.25	40.00	40.00			
C636	Distributor Cap	1.00	34.19	34.19	34.19			
BODY-TRIM -INTERIO	Body and Trim - Interior	0.00		95.55	0.00		HMP	
NCSI	The Vehicle needs an North Carolina State Inspection.- Requi							
NCSI	NCSI	1.00		9.50	9.50		JE	

10.15.2017

Free Form Note	Not running smooth, sometimes a erratic idle occurs- right sid							
Valve Cover Gasket(s)	Valve Cover Gaskets are leaking engine oil - Need to replace							
VALVE COVER GASKET	Valve Cover Gasket	0.60			105.00	63.00		BND
	Valve cover gasket	1.00	0.00		19.00	19.00		
SPARK PLUGS	Spark plugs, 4Cyl. replac	0.30			105.00	31.50		BND
	Spark plugs	4.00	8.55		8.55	34.20		
Oil & Filter - Service	The Vehicle needs an Engine Oil and Filter Service.-Engine Oil							
OIL SERVICE 4CYL	Oil Service 4 cyl, 5k	0.30			80.00	24.00		BND
BG-73053	BG-HI-LOW30 Synthetic Motor Oil	4.00	7.65		7.65	30.60		
	Oil Filter	1.00	9.00		9.00	9.00		
Air Filter - NR	The Air Filter needs replacement.--Every 15,000 miles The Air							
AIR FILTER	Air filter replace	0.30			105.00	31.50		BND
113 129 620	Air Filter	1.00	17.00		17.00	17.00		
Cooling System Repair	Cooling System Repair--- Noted -- Based on the problem - we							
COOLING SYSTEM SER	Cooling Sys - Service	1.80			105.00	189.00		BND
	upper radiator hose	1.00	8.59		15.24	15.24		
	lower hose	1.00	18.88		47.44	47.44		
	Cooling system flush kit	1.00	0.00		0.00	0.00		
	Radiator Flush cleaner	1.00	3.99		8.79	8.79		
1010801	Ball Joint - Lower - Front Suspension - ATM	1.00	20.72		20.72	20.72		
2601234	Ball Joint - Lower - Front Suspension - NCP	1.00	62.74		62.74	62.74		
Transmission - Leak	The Transmission has an Oil Leak and needs to be repaired.Re							
TRANSMISSION	Transmission - Leak	2.70			95.55	257.99		BND
30505	Auto Trans Fluid D4 GL-4 ATF - 1 Gallon 2045	1.00	87.00		87.00	87.00		
	Gasket and filter set	1.00	87.50		87.50	87.50		
	Transmission mount	1.00	61.54		61.54	61.54		
	Trans line -	1.00	111.11		111.11	111.11		
	Trans flush kit	1.00	0.00		0.00	0.00		
Brake Fluid Flush	Brake Fluid Flush--Replace Brake Fluid 1 Every 45,000 miles W							
BRAKES	Brake Fluid Flush	0.80			80.00	64.00		BND
BG-8402	BG-Brake Fluid-Dot 4	2.00	12.00		12.00	24.00		
Suspension Front	The Front Suspension needs to be checked for service and re							
CONTROL ARM BUSHIN	Control arm bushings	2.00			105.00	210.00		BND
	Front control arm - bushing rebuilt kit upper Front control arm	2.00	92.86		92.86	185.72		
Brakes	Need to rebuilt rear Ebrake system							
Tie rods	Tie rods are worn out and need to be replaced.Vehicle will ne							
TIE RODS	Tie rods	2.00			105.00	210.00		BND
	Outer tie rods	2.00	13.54		13.54	27.08		
Alignment - 4 Wheel	The vehicle needs a four wheel alignment.							
ALIGNMENT	Alignment Four Wheel	1.00			95.00	95.00		BND

Repair Order # 26372

1981 Fiat 124 Spider

License #
 ODO In:18544
 Color: Grey
 Mfg. Date:

Inv Date: 9/15/2017 @ 4:02pm

VIN: ZFAAS00B8B8180078

Engine: L4 2.0L, 1995cc, DOHC, GAS, FI

Trans:

Unit #

Service Writer: John Eliason

Status: Finished

Driver:

PO #

Vehicle Problems	Requests for Service	Services Performed	Qty	Price	Disc.	Ext
Check over -Basic Visual Inspection under hood and underbody.						0.00

- OK - Fair - Needs(NR) (ABCD)
- >> Review vehicle history ? ---
- 01- Engine Oil -----ok
- 02- Air Filter-----needs (A) dirty
- 03- Cabin Filter -----ok
- 04- Fuel Filter -----ok
- 05- Battery & Terminals-----ok
- 06- Wiper Blades -----ok
- 07- Power Steering Fluid -----n/a
- 08- Brake Fluid- Level Conditon---very low, needs (C) flush with brake job
- 09- Coolant & Hoses -----needs (A) both upper coolant hoses swelling
- 10- Trans Fluid - Auto / Manual /Diff---fair, needs (A) Trans fluid line damaged (soft line)
- 11- Brakes Front --Pad-%--Disc ?-----needs (B) <15%
- 12- Brakes Rear --Pad-%--Disc ?-----needs (B) <20%
- 13- Drive Belts -----ok
- 14- Engine Oil Leaks -----needs (C) both valve covers leaking into spark plugs and cam cover gaskets are leaking
- 15- Engine / Trans Mounts-----trans mount broken
- 16- Engine Timing Belt/Waterpump-----ok
- 17- Steering --Rack-Tie Rods-----needs (B) both front outer tie rod end bushings (damaged)
- 18- Suspension--FR & RR-----needs (B) both front upper control arm bushings, both front lower control arms bushings
- 19- Wheel bearings FR & RR-----ok
- 20- Tires ---FR & RR + Size-----ok 165/R 13/82 T
- 21- Lights--Signal--Side Marker- Other--ok
- 22- Headlight Lens-----ok
- 23- Power Windows / Locks --Mirrors--ok
- 24- Heating and Air Condition-----ok
- 25- Check Eng Light--SRS--ABS-----ok
- 26- Exterior paint / Interior-----needs (A) body/ paint damage by driver 'S side rear wheel well
- 27- Other -- Describe Below -----needs (B) Rear e-brake hardware rusted & structurally weak

Notes: Not running smooth, sometimes a erratic idle occurs
 - right side under passenger side has a creek(inspected)
 - radio antenna installed (its in the trunk in a plastic bag
 *DONE- loose bracket hanging under car (put back in place and tightened)
 - see if the pipe in the trunk can be retrofitted, its located with the battery
 *DONE- reattach passenger side door handle
 - passenger side pop out window handle needs to be re attached
 - brake light is on even when the handle is in the down position
 - Give a call with a quote before work is done!!!!!!!!!!!!
 -How much to replace top (just labor)

Valve Cover Gaskets are leaking engine oil						147.70
- Need to replace						
Labor Service - Valve Cover Gasket leaking, replace as needed BND						
Part	Valve cover gasket		1.00	19.00		63.00
						19.00

Repair Order # 26372

1981 Fiat 124 Splder

License #

Inv Date: 9/15/2017 @ 4:02pm

Labor Service - Spark plugs, 4 Cyl, replace as needed				31.50
Inspect wires or connectors as needed BND				
Part Spark plugs	4.00	8.55		34.20

The Vehicle needs an Engine Oil and Filter Service. 63.60

-Engine Oil is used to lubricate moving engine parts and operate some hydraulic parts of the engine itself. Engine oil performs many functions such as cleaning, cooling and lubricating. The engine oil should be routinely checked for proper level and replaced if beyond recommended time/mileage service interval or testing indicates loss of lubricating qualities.

Labor Service - Oil Service 4 cyl, 5k Service				24.00
-Change engine oil and filter, inspect air filter, replace if needed.				
-Inspect fluid levels, top off as needed				
-Inspect belts, brakes and cooling hoses.				
-Inspect battery and charging system.				
-Inspect steering and suspension, visually				
-Inspect wipers, top off washer fluid,				
-Inspect and adjust air pressure				
-Reset oil service light if needed. BND				
New BG-73053	BG-HI-LOW30 Synthetic Motor Oil	4.00	7.65	30.60
Part	Oil Filter	1.00	9.00	9.00

The Air Filter needs replacement. 48.50

-Every 15,000 miles
 The Air Cleaner Filter/Element prevents dirt and other material from entering the engine's intake system. A restricted Air Cleaner Filter may cause engine performance concerns such as low power, poor fuel economy or a rough running engine. Replace air cleaner filters in accordance with manufacturer service schedule.

Labor Service - Air filter replace, clean air box as needed, inspect intake boot. Inspect Throttle body BND				31.50
New 113 129 620	Air Filter	1.00	17.00	17.00

0.00

Cooling System Repair 343.93

— Noted – Based on the problem - we are unable to know if any additional damage has occurred until the problem has been repaired and vehicle becomes operational and can be tested.

- >
- > Replace uppler and lower radiator hoses
- > Flush coolant

Labor Service - Inspect cooling system, clean and flush system and replace coolant. The entire cooling system is first cleaned and then all debris and worn out coolant is completely flushed from the system. Then, fresh new premium coolant is added. Conditioners are also included to prevent rust and corrosion and BG Cooling System Sealer is also included to prevent leaks. The entire cooling system is first cleaned and then all debris and worn out coolant is completely flushed from the system. Then, fresh new premium coolant is added. Conditioners are also included to prevent rust and corrosion and BG Cooling System Sealer is also included to prevent leaks. BND				189.00
Part	upper radiator hose	1.00	15.24	15.24
Part	lower hose	1.00	47.44	47.44
Part	Cooling system flush kit	1.00	0.00	0.00
Part	Radiator Flush cleaner	1.00	8.79	8.79
New 1010801	Ball Joint - Lower - Front Suspension - ATM	1.00	20.72	20.72
New 2601234	Ball Joint - Lower - Front Suspension - NCP	1.00	62.74	62.74

0.00

Based on our inspection we recommend that: The Transmission has an Oil Leak and needs to be repaired. 605.14

Replace leaking pan gasket, clean filter and refill with clean fluid.
 --->> noted 11/3/2014 HNR---

Repair Order # 26372

1981 Fiat 124 Spider

License #

Inv Date: 9/15/2017 @ 4:02pm

- Need to replace trans mount
- Need to change filter and gasket -
- Need to flush fluid
- Need to repair leaky line

				257.99	
Labor Service - Transmission - Leak					
- replace needed trans mount					
- replace gasket and filter as needed					
- flush and change trans fluid BND					
New	30505	Auto Trans Fluid D4 GL-4 ATF - 1 Gallon 2045	1.00	87.00	87.00
Part		Gasket and filter set	1.00	87.50	87.50
Part		Transmission mount	1.00	61.54	61.54
Part		Trans line -	1.00	111.11	111.11
Part		Trans flush kit	1.00	0.00	0.00

0.00

Brake Fluid Flush

--Replace Brake Fluid 1 Every 45,000 miles
 When the pedal is depressed, the master cylinder transfers Brake Fluid to apply the calipers or wheel cylinders, slowing or stopping the vehicle. Brake Fluid may lose some lubricating or stability properties with time and use. High heat from brakes coupled with water vapor from the air can wear down the fluid. Determining fluid condition and servicing, replacing or flushing may be a repair as prescribed by manufacturer service instructions.

				64.00	
Labor Service - Brake Fluid Flush. Recommended every two years or as needed.					
Flush old fluid from brake master cylinder and brake hydraulics.. Inspect reservoir and cap, inspect brake lines and brake master cylinder . BND					
New	BG-8402	BG-Brake Fluid-Dot 4	2.00	12.00	24.00

0.00

The Front Suspension needs to be checked for service and repairs.

- Need to replace upper control arm bushings
- Need to replace front lower control arm bushings

				210.00	
Labor Service - Control arm bushings, remove control arms, press bushings out and install new, Reinstall control arms.					
-- Note : Four wheel Alignment is reconnected with this Service. BND					
Part		Front control arm - bushing rebuilt kit upper	2.00	92.86	185.72
		Front control arm bushing kit lower			

0.00

Need to rebuilt rear Ebrake system

0.00

Tie rods are worn out and need to be replaced.

Vehicle will need an alignment after this serviced is completed.

				210.00	
Labor Service - Tie rods. Replace Steering Tie Rods as needed.					
Inspect ball joints, control arms and bushings. BND					
Part		Outer tie rods	2.00	13.54	27.08

0.00

The vehicle needs a four wheel alignment.

				95.00	
Labor Service - Align All Wheels -Recommended every two years.				-10.00	95.00
Electronically align all wheels. Set caster, camber and toe in. Check and adjust air pressure as needed, inspect tires, steering and suspension. -- Test Drive. BND					

0.00

0.00

Repair Order # 26372

1981 Fiat 124 Spider

License #

Inv Date: 9/15/2017 @ 4:02pm

The Vehicle needs to be Washed ,and Fully Detailed. 0.00
 --Clean engine compartment
 --Clean under body
 --Clean interior

Additional parts not included in estimate -----				139.58
Labor Service - Part order BND				
<i>Part</i>	<i>Drive belt</i>	1.00	21.00	0.00
				21.00
<i>Part</i>	<i>v belt</i>	1.00	30.99	30.99
<i>Part</i>	<i>gasket material</i>	1.00	12.59	12.59
<i>Part</i>	<i>gasket material</i>	1.00	45.00	45.00
<i>Part</i>	<i>Additional hardware used</i>	1.00	30.00	30.00
	<i>-- nuts bolts - clamps</i>			

Notes: added reverse light 1057 bulb 0.00

0.00

The Suspension Ball Joints are worn out and Need to be replaced. 331.66
Vehicle will need an Alignment when complete.

Labor Service - Ball Joints replace as needed TNR				
<i>New</i>	<i>621318 Lower Ball joint</i>	2.00	60.83	210.00
	<i>- Installed one ball joint</i>			121.66

0.00

-- 600 Credit per customer downpayment 0.00

- Recommended Repairs and Services:**
- Based on our inspection we recommend that: Brake Fluid Flush 88.00
 --Replace Brake Fluid 1 Every 45,000 miles
 When the pedal is depressed, the master cylinder transfers Brake Fluid to apply the calipers or wheel cylinders, slowing or stopping the vehicle. Brake Fluid may lose some lubricating or stability properties with time and use. High heat from brakes coupled with water vapor from the air can wear down the fluid. Determining fluid condition and servicing, replacing or flushing may be a repair as prescribed by manufacturer service instructions.
 ----- >> noted 11/3/2014 HNR---
 - Based on our inspection we recommend that: The Windshield Wiper Blades should be inspected to avoid problems with vision in poor driving conditions. 76.23
 ----- >> noted 11/3/2014 HNR---
 - Based on our inspection we recommend that: Valve Cover Gaskets are leaking engine oil 156.66
 - Need to replace
 ----- >> noted 11/3/2014 HNR---
 - Based on our inspection we recommend that: Vehice Paint is in good condition, suggest to color sand, buff, polish and wax. 353.54
 ----- >> noted 11/3/2014 HNR---
 - Due 12/22/2017 - Based on our inspection we recommend that: Convertible top, check operation 1,070.71
 - Due 1/21/2018 - Based on our inspection we recommend that: The Front Brakes need service.Need to clean rust from brakes 199.27
 ----- >> noted 11/3/2014 HNR---
 - Due 1/23/2018 - Based on our inspection we recommend that: The Rear Brakes need to be serviced.- Need to clean rust from brakes 200.81
 ----- >> noted 11/3/2014 HNR---

Import Performance INC
 5618 Hillsborough Street
 Raleigh, NC 27606
 (919) 854-2626
 Service@importperformance-nc.com
 www.importcarnc.com

Repair Order # 26372

1981 Fiat 124 Spider

License #

Inv Date: 9/15/2017 @ 4:02pm

Continued from previous page

- 600⁰⁰

<p>Warranty Standard Warranty is 12 months or 12k miles</p> <p>I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.</p> <p>X _____ Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.</p> <p>X _____ Customer acknowledges receipt of merchandise and services.</p>	<p>Tax Breakdown: Default Sales Tax 193.43</p>	<p>Repair Order Summary:</p> <table> <tr><td>Parts</td><td>1,055.32</td></tr> <tr><td>Labor</td><td>1,385.99</td></tr> <tr><td>Fluids</td><td>54.60</td></tr> <tr><td>Supply Charge/H</td><td>39.25</td></tr> <tr><td>Sub Total</td><td>2,535.16</td></tr> <tr><td>Sales Tax (DEF)</td><td>193.43</td></tr> <tr><td>Total</td><td>2,728.59</td></tr> </table>	Parts	1,055.32	Labor	1,385.99	Fluids	54.60	Supply Charge/H	39.25	Sub Total	2,535.16	Sales Tax (DEF)	193.43	Total	2,728.59
Parts	1,055.32															
Labor	1,385.99															
Fluids	54.60															
Supply Charge/H	39.25															
Sub Total	2,535.16															
Sales Tax (DEF)	193.43															
Total	2,728.59															

Discard old parts

Original Estimate:

2128 ⁵⁹/₁₀₀

Import Performance INC
 5618 Hillsborough Street
 Raleigh, NC 27606
 (919) 854-2626
 Service@importperformance-nc.com
 www.importcarnc.com

Repair Order # 19495

1981 Fiat 124 Spider

License# _____ Inv Date: 10/30/2014 @ 10:25am

Replace leaking pan gasket, clean filter and refill with clean fluid.

Labor Service - Transmission - Leak HNR New 30505 Auto Trans Fluid D4 GL-4 ATF - 1 Gallon 2045	1.00	87.00	143.33 87.00
Valve Cover Gaskets are leaking engine oil - Need to replace			156.66
Labor Service - Valve Cover Gasket leaking, replace as needed HNR Part Valve Cover Gaskets	2.00	21.00	114.66 42.00
Vehicle Paint is in good condition, suggest to color sand, buff, polish and wax.			353.54
Labor Service - Paint recondition - - Wash car - Clay bar painted surface - Colorsand exterior paint - Buff - Polish and wax paint - Clean and Rustproof underbody - Clean and condition engine Compartment HNR			353.54

Warranty

Standard Warranty is 12 months or 12k miles

I hereby authorize the repair work listed herein, including sublet work along with necessary materials. You and your employees may operate the described vehicle for purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle for the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle in the event of fire, theft, accident or any other cause beyond your control. Customer shall pay all collection costs and/or attorneys fees in the event that default is made in any payment due to us. Vehicle is returned to customer without repair service being performed, a diagnostic and handling fee shall be charged. I have read and understand the above and acknowledge repair estimate.

X _____
 Terms: CASH on delivery. Payment due prior to authorization. Vehicles left after repair is complete may be subject to storage fee.

X _____
 Customer acknowledges receipt of merchandise and services.

Estimate not pay.

Tax Breakdown:
 Default Sales Tax 51.69

Repair Order Summary:

Parts 642.99
 Labor 1,497.26
 Fluids 24.00
 Supply Charge/H 39.25

Sub Total 2,203.50
 Sales Tax (DEF) 51.69

Discard old

Original Estimate: 2,255.19

Total 2,255.19

10 SPO...
 VA 22...
 40-943-5889
 330089002450
 2450

Repair Order # 19495



1981 Fiat 124 Spider

VIN:
 Engine: L4 2.0L, 1995cc, DOHC, GAS, FI
 Trans:

License#
 ODO In: 18234
 Color: Grey
 Mfg. Date:
 Unit #

Inv Date: 10/30/2014 @ 10:25am
 Service Writer: Ronald Crane
 Status: Waiting for Authorization
 Driver:
 PO #

Vehicle Problems	Requests for Service	Services Performed	Qty	Price	Ext
No Start					95.55
Labor Service - Diagnose time, ***** HNR					95.55

The Fuel Pump needs to be repaired or replaced. 934.62

Technician states that the fuel pump relay and fuel pump have failed.
 The fuel pump has locked up and overloaded the fuel pump relay.
 The engine was started with an alternative fuel source and mechanical function sounds OK.

However, the spark plugs are fouled and the injectors are partially stopped up from expired fuel. The fuel tank must be drained and injectors cleaned as part of this repair.

Labor Service - Fuel System - Repair					477.75
Drain fuel tank. Clean Injectors and fuel Lines. Replace Fuel Pump, Fuel Filter, and Fuel Pump Relay. HNR					
New	0332514121	Relay Fuel Injection System 2060	1.00	153.00	153.00
New	69430	Fuel Pump 2040	1.00	236.22	236.22
New	1263	Spark Plug BP6ET NGK 2045	1.00	5.33	5.33
New	71028	Fuel Filter	1.00	22.32	22.32
New	GASOLINE	Fuel Needed For Repairs	1.00	40.00	40.00

-->>Estimate on repairs below <<-- **0.00**

Brake Fluid Flush 88.00

—Replace Brake Fluid 1 Every 45,000 miles
 When the pedal is depressed, the master cylinder transfers Brake Fluid to apply the callpers or wheel cylinders, slowing or stopping the vehicle. Brake Fluid may lose some lubricating or stability properties with time and use. High heat from brakes coupled with water vapor from the air can wear down the fluid. Determining fluid condition and servicing, replacing or flushing may be a repair as prescribed by manufacturer service instructions.

Labor Service - Brake Fluid Flush. Recommended every two years or as needed. Flush old fluid from brake master cylinder and brake hydraulics. Inspect reservoir and cap, inspect brake lines and brake master cylinder. HNR					64.00
New	BG-8402	BG-Brake Fluid-Dot 4	2.00	12.00	24.00

The Front Brakes need service. 114.66

Labor Service - Brake Inspection. Remove calipers, clean rust and lubricate all moving parts. HNR					114.66
--	--	--	--	--	--------

The Rear Brakes need to be serviced. 114.66

Labor Service - Brake Inspection. Remove calipers, clean rust and lubricate all parts. HNR					114.66
---	--	--	--	--	--------

The Windshield Wiper Blades should be inspected to avoid problems with vision in poor driving conditions. 76.23

Labor Service - Wiper System Replace Blades HNR					19.11
New	16-2213	Wiper Blade	2.00	28.56	57.12

The Transmission has an Oil Leak and needs to be repaired. 230.33

European Auto Sport, Inc.

5 Stuarts Draft Hwy
Suite 105
Waynesboro, VA 22980
Phone: 540-943-5889 FAX: 540-949-7950

Invoice No.

210915006

Page 2

Order Date 09/15/11 02:05 pm
Completed: 12/01/11 02:04 pm

R&R Radiator

0144466560	Water "Tee"-S	1.0 @	61.93 =\$	61.93	
0141887040	Water T Gasket-S	1.0 @	2.58 =\$	2.58	
16100	Shipping & Freight-N	1.0 @	7.75 =\$	7.75	
110200	Kost Antifreeze-N	1.5 @	14.84 =\$	22.26	94.52

Radiator Repair
Rod out radiator core.

Sublet: \$113.00

Payments to European Auto Sport, Inc.

Status: Completed Work Order

Payments:

Cost Summary

Labor	279.00
Parts	203.86
Sublet	113.00
Haz Waste	1.00
Shop Supplies	4.08
Tax	10.39
Total	\$611.33
Payments	0.00
Bal Due	611.33

Thank you for choosing European Auto Sport, Inc.

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature)

Repair Order # 26372

1981 Fiat 124 Spider

VIN: ZFAAS00B8B8180078
 Engine: L4 2.0L, 1995cc, DOHC, GAS, FI
 Trans:

License #
 ODO In:18544
 Color: Grey
 Mfg. Date:
 Unit #

Inv Date: 9/15/2017 @ 4:02pm
 Service Writer: John Eliason
 Status: Work In Progress
 Driver:
 PO #

Vehicle Problems	Requests for Service	Services Performed	Qty	Price	Disc.	Ext
Check over -Basic Visual Inspection under hood and underbody.						
						0.00

- _____OK - Fair - Needs(NR) (ABCD)
- _____ >> Review vehicle history ? _____
- 01- Engine Oil _____ok
- 02- Air Filter _____needs (A) dirty
- 03- Cabin Filter _____ok
- 04- Fuel Filter _____ok
- 05- Battery & Terminals _____ok
- 06- Wiper Blades _____ok
- 07- Power Steering Fluid _____n/a
- 08- Brake Fluid- Level Conditon _____very low, needs (C) flush with brake job
- 09- Coolant & Hoses _____needs (A) both upper coolant hoses swelling
- 10- Trans Fluid - Auto / Manual /Diff _____fair, needs (A) Trans fluid line damaged (soft line)
- 11- Brakes Front -Pad-%-Disc ? _____needs (B) <15% _____
- 12- Brakes Rear -Pad-%-Disc ? _____needs (B) <20% _____
- 13- Drive Belts _____ok
- 14- Engine Oil Leaks _____needs (C) both valve covers leaking into spark plugs and cam cover gaskets are leaking
- 15- Engine / Trans Mounts _____trans mount broken
- 16- Engine Timing Belt/Waterpump _____ok
- 17- Steering -Rack-Tie Rods _____needs (B) both front outer tie rod end bushings (damaged)
- 18- Suspension-FR & RR _____needs (B) both front upper control arm bushings, both front lower control arms bushings
- 19- Wheel bearings FR & RR _____ok
- 20- Tires _____FR & RR + Size _____ok 165/R 13/82 T
- 21- Lights-Signal-Side Marker- Other _____ok
- 22- Headlight Lens _____ok
- 23- Power Windows / Locks -Mirrors _____ok
- 24- Heating and Air Condition _____ok
- 25- Check Eng Light-SRS-ABS _____ok
- 26- Exterior paint / Interior _____needs (A) body/ paint damage by driver 'S side rear wheel well
- 27- Other - Describe Below _____needs (B) Rear e-brake hardware rusted & structurally weak

Notes: Not running smooth, sometimes a erratic idle occurs
 - right side under passenger side has a creek(inspected)
 - radio antenna installed (its in the trunk in a plastic bag
 *DONE- loose bracket hanging under car (put back in place and tightened)
 - see if the pipe in the trunk can be retrofitted, its located with the battery
 *DONE- reattach passenger side door handle
 - passenger side pop out window handle needs to be re attached
 - brake light is on even when the handle is in the down position
 - Give a call with a quote before work is done!!!!!!!
 -How much to replace top (just labor)

0.00

Valve Cover Gaskets are leaking engine oil
 - Need to replace

0.00
147.70

Labor Service - Valve Cover Gasket leaking, replace as needed TNR

	1.00	19.00				63.00
Part		Valve cover gasket				19.00

Import Performance INC

5618 Hillsborough Street
 Raleigh, NC 27606
 (919) 854-2626
 Service@Importperformance-nc.com
 www.importcarnc.com

147
 605
 400
 237

Repair Order # 26372

1981 Fiat 124 Spider

License #

Inv Date: 9/15/2017 @ 4:02pm

Labor Service - Spark plugs, 4 Cyl, replace as needed				31.50
Inspect wires or connectors as needed TNR				
Part Spark plugs	4.00	8.55		34.20

The Vehicle needs an Engine Oil and Filter Service.

-Engine Oil is used to lubricate moving engine parts and operate some hydraulic parts of the engine itself. Engine oil performs many functions such as cleaning, cooling and lubricating. The engine oil should be routinely checked for proper level and replaced if beyond recommended time/mileage service interval or testing indicates loss of lubricating qualities.

Labor Service - Oil Service 4 cyl, 5k Service				24.00
-Change engine oil and filter, inspect air filter, replace if needed.				
-Inspect fluid levels, top off as needed				
-Inspect belts, brakes and cooling hoses.				
-Inspect battery and charging system.				
-Inspect steering and suspension, visually				
-Inspect wipers, top off washer fluid,				
-Inspect and adjust air pressure				
-Reset oil service light if needed. TNR				
New BG-73053	BG-HI-LOW30 Synthetic Motor Oil	4.00	7.65	30.60
Part Oil Filter		1.00	9.00	9.00

The Air Filter needs replacement.

-Every 15,000 miles
 The Air Cleaner Filter/Element prevents dirt and other material from entering the engine's intake system. A restricted Air Cleaner Filter may cause engine performance concerns such as low power, poor fuel economy or a rough running engine. Replace air cleaner filters in accordance with manufacturer service schedule.

Labor Service - Air filter replace, clean air box as needed, inspect intake boot. Inspect Throttle body TNR				31.50
New 113 129 620	Air Filter	1.00	17.00	17.00

Cooling System Repair

-- Noted -- Based on the problem - we are unable to know if any additional damage has occurred until the problem has been repaired and vehicle becomes operational and can be tested.

- > Replace upper and lower radiator hoses
- > Flush coolant

Labor Service - Inspect cooling system, clean and flush system and replace coolant. The entire cooling system is first cleaned and then all debris and worn out coolant is completely flushed from the system. Then, fresh new premium coolant is added. Conditioners are also included to prevent rust and corrosion and BG Cooling System Sealer is also included to prevent leaks. The entire cooling system is first cleaned and then all debris and worn out coolant is completely flushed from the system. Then, fresh new premium coolant is added. Conditioners are also included to prevent rust and corrosion and BG Cooling System Sealer is also included to prevent leaks. TNR				189.00
Part upper radiator hose	1.00	15.24		15.24
Part lower hose	1.00	47.44		47.44

Based on our inspection we recommend that: The Transmission has an Oil Leak and needs to be repaired.

Replace leaking pan gasket, clean filter and refill with clean fluid.

--> noted 11/3/2014 HNR---

- Need to replace trans mount
- Need to change filter and gasket -
- Need to flush fluid
- Need to repair leaky line

0.00
 605.14

Repair Order # 26372

1981 Fiat 124 Spider

License #

Inv Date: 9/15/2017 @ 4:02pm

Labor Service - Transmission - Leak
 -- replace needed trans mount
 -- replace gasket and filter as needed
 -- flush and change trans fluid TNR

New 30505	Auto Trans Fluid D4 GL-4 ATF - 1 Gallon 2045	1.00	87.00	87.00
Part	Gasket and filter set	1.00	87.50	87.50
Part	Transmission mount	1.00	61.54	61.54
Part	Trans line -	1.00	111.11	111.11

*Flushing
16 quarts*

257.99
0.00

Based on our inspection we recommend that: The Front Brakes need service. Need to clean rust from brakes

-->> noted 11/3/2014 HNR--

Labor Service - Brake Inspection.

Remove calipers, clean rust and lubricate all moving parts.

Part	Brake disc	2.00	27.69	55.38
Part	Brake pads - front	1.00	29.23	29.23

2015

199.27
114.66

Based on our inspection we recommend that: The Rear Brakes need to be serviced.- Need to clean rust from brakes

-->> noted 11/3/2014 HNR--

Labor Service - Brake Inspection.

Remove calipers, clean rust and lubricate all parts.

Part	Brake pads rear	1.00	30.77	30.77
Part	Brake disc - rear	2.00	27.69	55.38

1.00 30.77

200.81
114.66

Brake Fluid Flush

--Replace Brake Fluid 1 Every 45,000 miles

When the pedal is depressed, the master cylinder transfers Brake Fluid to apply the calipers or wheel cylinders, slowing or stopping the vehicle. Brake Fluid may lose some lubricating or stability properties with time and use. High heat from brakes coupled with water vapor from the air can wear down the fluid. Determining fluid condition and servicing, replacing or flushing may be a repair as prescribed by manufacturer service instructions.

Labor Service - Brake Fluid Flush. Recommended every two years or as needed.

Flush old fluid from brake master cylinder and brake hydraulics.. Inspect reservoir and cap, inspect brake lines and brake master cylinder. TNR

New BG-8402	BG-Brake Fluid-Dot 4	2.00	12.00	24.00
-------------	----------------------	------	-------	-------

88.00

The Front Suspension needs to be checked for service and repairs.

- Need to replace upper control arm bushings
- Need to replace front lower control arm bushings

Labor Service - Control arm bushings, remove control arms, press bushings out and install new, Reinstall control arms.

-- Note : Four wheel Alignment is reconnected with this Service. TNR

Part	Front control arm - bushing rebuilt kit upper	2.00	92.86	185.72
	Front control arm bushing kit lower			

400

395.72
210.00

Need to rebuilt rear Ebrake system

0.00
0.00

Tie rods are worn out and need to be replaced.

Vehicle will need an alignment after this serviced is completed.

Labor Service - Tie rods. Replace Steering Tie Rods as needed.

Inspect ball joints, control arms and bushings. TNR

Part	Outer tie rods	2.00	13.54	27.08
------	----------------	------	-------	-------

237.08
210.00

Repair Order # 26372

1981 Fiat 124 Spider

License #

Inv Date: 9/15/2017 @ 4:02pm

The vehicle needs a four wheel alignment.

Labor Service - Align All Wheels -Recommended every two years.
 Electronically align all wheels. Set caster, camber and toe in. Check and adjust air pressure as needed, inspect tires, steering and suspension. -- Test Drive. TNR

-10.00

0.00

95.00

95.00

Convertible top, check operation

Labor Service - Convertible top repairs TNR
 Part Convertible top

1.00 335.71

0.00

1,070.71

735.00

335.71

0.00

The Vehicle needs to be Washed ,and Fully Detailed.

0.00

- Clean engine compartment
- Clean under body
- Clean interior

Recommended Repairs and Services:

- Based on our inspection we recommend that: Brake Fluid Flush 88.00
 --Replace Brake Fluid 1 Every 45,000 miles
 When the pedal is depressed, the master cylinder transfers Brake Fluid to apply the calipers or wheel cylinders, slowing or stopping the vehicle. Brake Fluid may lose some lubricating or stability properties with time and use. High heat from brakes coupled with water vapor from the air can wear down the fluid. Determining fluid condition and servicing, replacing or flushing may be a repair as prescribed by manufacturer service instructions.
 ----- >> noted 11/3/2014 HNR---
- Based on our inspection we recommend that: The Windshield Wiper Blades should be inspected to avoid problems with vision in poor driving conditions. 76.23
 ----- >> noted 11/3/2014 HNR---
- Based on our inspection we recommend that: Valve Cover Gaskets are leaking engine oil 156.66
 - Need to replace
 ----- >> noted 11/3/2014 HNR---
- Based on our inspection we recommend that: Vehice Paint is in good condition, suggest to color sand, buff, polish and wax. 353.54
 ----- >> noted 11/3/2014 HNR---

Warranty

Standard Warranty is 12 months or 12k miles

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereon. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate

Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee

Customer acknowledges receipt of merchandise and services.

3700
 1100
 2300

includes TOP Swiss

Repair Order Summary:

Parts 1,208.30
 Labor 2,140.31
 Fluids 54.60
 Supply Charge/H 39.25

Tax Breakdown:
 Default Sales Tax 263.74

Sub Total 3,442.46
 Sales Tax (DEF) 263.74

Total 3,706.20

Repair Order # 19495

~~XXXXXXXXXX~~
~~XXXXXXXXXX~~
~~XXXXXXXXXX~~
~~XXXXXXXXXX~~

1981 Fiat 124 Spider

VIN:
 Engine: L4 2.0L, 1995cc, DOHC, GAS, FI
 Trans:

License #
 ODO In:18234
 Color: Grey
 Mfg. Date:
 Unit #

Inv Date: 10/30/2014 @ 10:25am
 Service Writer: Ronald Crane
 Status: Work In Progress
 Driver:
 PO #

Vehicle Problems	Requests for Service	Services Performed	Qty	Price	Disc.	Ext
No Start						95.55
	Labor Service - Diagnose time, ***** HNR					95.55
<hr/>						968.81

The Fuel Pump needs to be repaired or replaced.

Technician states that the fuel pump relay and fuel pump have failed.
 The fuel pump has locked up and overloaded the fuel pump relay.
 The engine was started with an alternative fuel source and mechanical function sounds OK.

However, the spark plugs are fouled and the injectors are partially stopped up from expired fuel. The fuel tank must be drained and injectors cleaned as part of this repair.

— Customer approved listed repairs - 11/3/2014- JE-

Labor Service - Fuel System - Repair						477.75
Drain fuel tank. Clean Injectors and fuel Lines. Replace Fuel Pump, Fuel Filter, and Fuel Pump Relay. HNR						
New 0 332 514 121	Relay Fuel Injection System 2060		1.00	153.00		153.00
New 69 430	Fuel Pump 2040		1.00	236.22		236.22
New 1263	Spark Plug BP6ET NGK 2045		1.00	5.33		5.33
New 71 028	Fuel Filter		1.00	22.32		22.32
New GASOLINE	Fuel Needed For Repairs		1.00	40.00		40.00
New C636	Distributor Cap		1.00	34.19		34.19

Labor Service - Technician cleaned entire trunk compartment while service to fuel tank was performed.
 Once complete, technician then removed all rust and corrosion.
 After all surfaces were cleaned, the trunk was repainted with trunk liner paint.
 HNR

The Vehicle needs an North Carolina State Inspection.						9.50
- Required Yearly when vehicles registration is renewed.						
Labor Service - NCSI -> North Carolina Ste Inspection. BND					-20.50	9.50

----->>Estimate on repairs below <<----- 0.00

--Date -- Time -- By -- Note 0.00

11/12/2014 - emailed customer estimate and check list - JE-
 11/3/2014 - 12.45 - customer approved fuel delivery repairs. - JE
 11/3/2014 - emailed revised estimate - JE-
 This email is authorization to proceed with fuel pump work and NC vehicle inspection.
 \$1104.83 plus inspection charges.
 Thanks for your help.
 Aubrey Keen

Sent from AOL Mobile Mail

Import Performance INC
 5618 Hillsborough Street
 Raleigh, NC 27606
 (919) 854-2626
 Service@Importperformance-nc.com
 www.importcarnc.com

Repair Order # 19495

1981 Fiat 124 Spider

License #

Inv Date: 10/30/2014 @ 10:25am

Recommended Repairs and Services:

- Based on our inspection we recommend that: Brake Fluid Flush 88.00
 --Replace Brake Fluid 1 Every 45,000 miles
 When the pedal is depressed, the master cylinder transfers Brake Fluid to apply the calipers or wheel cylinders, slowing or stopping the vehicle. Brake Fluid may lose some lubricating or stability properties with time and use. High heat from brakes coupled with water vapor from the air can wear down the fluid. Determining fluid condition and servicing, replacing or flushing may be a repair as prescribed by manufacturer service instructions.
 ----- >> noted 11/3/2014 HNR---
- Based on our inspection we recommend that: The Front Brakes need service. Need to clean rust from brakes 114.66
 ----- >> noted 11/3/2014 HNR---
- Based on our inspection we recommend that: The Rear Brakes need to be serviced.- Need to clean rust from brakes 114.66
 ----- >> noted 11/3/2014 HNR---
- Based on our inspection we recommend that: The Windshield Wiper Blades should be inspected to avoid problems with vision in poor driving conditions. 76.23
 ----- >> noted 11/3/2014 HNR---
- Based on our inspection we recommend that: The Transmission has an Oil Leak and needs to be repaired. 230.33
 Replace leaking pan gasket, clean filter and refill with clean fluid.
 ----- >> noted 11/3/2014 HNR---
- Based on our inspection we recommend that: Valve Cover Gaskets are leaking engine oil 156.66
 - Need to replace
 ----- >> noted 11/3/2014 HNR---
- Based on our inspection we recommend that: Vehicle Paint is in good condition, suggest to color sand, buff, polish and wax. 353.54
 ----- >> noted 11/3/2014 HNR---

Warranty


Standard Warranty is 12 months or 12k miles

Estimate only, do not pay.

Repair Order Summary:

Parts	491.06
Labor	582.80
Supply Charge/H	39.25

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorney fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

X 
 Terms of sale unless arranged otherwise made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

Tax Breakdown:

Default Sales Tax 38.06

X _____
 Customer acknowledges receipt of merchandise and services

Sub Total	1,113.11
Sales Tax (DEF)	38.06

Repair Order # 19495

inspectio
 --->> noted 11/3

1981 Fiat 124 Spider

VIN:
 Engine: L4 2.0L, 1995cc, DOHC, GAS, FI
 Trans:

License#
 ODO In: 18234
 Color: Grey
 Mfg. Date:
 Unit #

Inv Date: 10/30/2014 @ 10:25am
 Service Writer: Ronald Crane
 Status: Waiting for Authorization
 Driver:
 PO #

Vehicle Problems	Requests for Service	Services Performed	Qty	Price	Ext
No Start					95.55
Labor Service - Diagnose time, ***** HNR					95.55
The Fuel Pump needs to be repaired or replaced.					934.62

Technician states that the fuel pump relay and fuel pump have failed.
 The fuel pump has locked up and overloaded the fuel pump relay.
 The engine was started with an alternative fuel source and mechanical function sounds OK.

However, the spark plugs are fouled and the injectors are partially stopped up from expired fuel. The fuel tank must be drained and injectors cleaned as part of this repair.

Labor Service - Fuel System - Repair					477.75
Drain fuel tank. Clean Injectors and fuel Lines. Replace Fuel Pump, Fuel Filter, and Fuel Pump Relay. HNR					
New	0332514121	Relay Fuel Injection System 2060	1.00	153.00	153.00
New	69430	Fuel Pump 2040	1.00	236.22	236.22
New	1263	Spark Plug BP6ET NGK 2045	1.00	5.33	5.33
New	71028	Fuel Filter	1.00	22.32	22.32
New	GASOLINE	Fuel Needed For Repairs	1.00	40.00	40.00
>> Estimate on repairs below <<					0.00

-Date - Time - By - Note

- 11/2/2014 - emailed customer estimate and check list - JE-
- 11/3/2014 - 12.45 - customer approved fuel delivery repairs. - JE
- 11/3/2014 - emailed revised estimate - JE-

Recommended Repairs and Services:

- Based on our inspection we recommend that: Brake Fluid Flush
 -Replace Brake Fluid 1 Every 45,000 miles
 When the pedal is depressed, the master cylinder transfers Brake Fluid to apply the calipers or wheel cylinders, slowing or stopping the vehicle. Brake Fluid may lose some lubricating or stability properties with time and use. High heat from brakes coupled with water vapor from the air can wear down the fluid. Determining fluid condition and servicing, replacing or flushing may be a repair as prescribed by manufacturer service instructions.
 --->> noted 11/3/2014 HNR--- 88.00
- Based on our inspection we recommend that: The Front Brakes need service. Need to clean rust from brakes
 --->> noted 11/3/2014 HNR--- 114.66
- Based on our inspection we recommend that: The Rear Brakes need to be serviced. - Need to clean rust from brakes
 --->> noted 11/3/2014 HNR--- 114.66
- Based on our inspection we recommend that: The Windshield Wiper Blades should be inspected to avoid problems with vision in poor driving conditions.
 --->> noted 11/3/2014 HNR--- 76.23
- Based on our inspection we recommend that: The Transmission has an Oil Leak and needs to be repaired.
 Replace leaking pan gasket, clean filter and refill with clean fluid.
 --->> noted 11/3/2014 HNR--- 230.33
- Based on our inspection we recommend that: Valve Cover Gaskets are leaking engine oil
 -Need to replace
 --->> noted 11/3/2014 HNR--- 156.66

Import Performance INC
 5618 Hillsborough Street
 Raleigh, NC 27606
 (919) 854-2626
 Service@Importperformance-nc.com
 www.importcarnc.com

Repair Order # 19495

1981 Fiat 124 Spider

License#

Inv Date: 10/30/2014 @ 10:25am

353.54

Inspection we recommend that: Vehicle Paint is in good condition, suggest to color sand, buff, polish and wax.

--->> noted 11/3/2014 HNR---

* Also authorize vehicle inspection

[Handwritten Signature]

[Handwritten checkmark]

<p>Warranty Standard Warranty is 12 months or 12k miles</p> <p>I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.</p> <p>X <i>[Handwritten Signature]</i></p> <p>Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.</p> <p>X _____</p> <p>Customer acknowledges receipt of merchandise and services.</p>	<p>Estimate only, do not pay.</p> <p>Tax Breakdown: Default Sales Tax 35.41</p>	<p>Repair Order Summary:</p> <table> <tr><td>Parts</td><td>456.87</td></tr> <tr><td>Labor</td><td>573.30</td></tr> <tr><td>Supply Charge/H</td><td>39.25</td></tr> <tr><td>Sub Total</td><td>1,069.42</td></tr> <tr><td>Sales Tax (DEF)</td><td>35.41</td></tr> <tr><td>Total</td><td>1,104.83</td></tr> </table>	Parts	456.87	Labor	573.30	Supply Charge/H	39.25	Sub Total	1,069.42	Sales Tax (DEF)	35.41	Total	1,104.83
Parts	456.87													
Labor	573.30													
Supply Charge/H	39.25													
Sub Total	1,069.42													
Sales Tax (DEF)	35.41													
Total	1,104.83													
<p>Page 2 of 2</p>	<p>Discard old parts</p>	<p>Original Estimate: 2,255.19</p>												

Import Performance INC
 5618 Hillsborough Street
 Raleigh, NC 27606
 (919) 854-2626
 Service@Importperformance-nc.com
 www.importcarnc.com

Repair Order # 32928

1981 Fiat 124 Spider

VIN: ZFAAS00B8B8180078

Engine: L4 2.0L, 122cid, DOHC, GAS, FI

Trans:

License #

ODO In:0

Color:

Mfg. Date:

Unit #

Inv Date: 12/03/2020 @ 2:13pm

Service Writer: John Elliason

Status: 5. Work In Progress 11/12/1.0

Driver:

PO #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
->> blower fan is not working						0.00
->> Lights for the gauges are not working						0.00
->> When ignition off and turn park light clock stops						0.00
						0.00
->> see if any coolant leaks , some spots showed - review						0.00
						0.00

The Vehicle needs the following General Repairs.

1,008.50

Check blower motor
 Remove as needed
 Found locked up electrical blower motor
 Replace with used as needed.
 Had to remove ebrake
 Had to remove shifter assembly
 Had to remove steering column
 Had to remove center console

Check instrument cluster lights / fiber optic, reostat delete
 Repair as needed - rewire as needed

Check clock operation
 rewire as needed

Checked coolant leak
 tighten loose hose clamp as needed
 pressure checked - OK

Labor Service - General Repairs
 New FIAT 124 SPIDER 76 B FIAT 124 SPIDER 76 BLOWER BOX AND
 MOTOR FAN

6.50 1.00 119.00 235.00

773.50
 235.00